


The Problem

with typical ambulance construction

Exterior Skins
Attached with
Tape and Glue

Skip Welded
Framework

Slotted-Style
Corner Posts



Cabinets
Screwed to Frame

Wood Cabinetry

Design Lacks
Structural Integrity

The

EXCELLANCE


Aluminum Cabinetry
Welded to Frame

Solution

Continuously
Welded Seams



12 + 4"
24 + 6"
Aluminum Gussets



Pulse Welded Structural
Members to Exterior Skin

Accidents will happen. The solution is to rely on the safest, most durable module possible: one that saves both lives and money!

EXCELLANCE builds the strongest module possible. With quality workmanship, reliability, and dependability, it is a sound investment year after year.

EXCELLANCE

EXCELLANCE has manufactured the finest emergency vehicles since 1975. Our reputation throughout the industry is reflected in our quality craftsmanship, superior durability, and stellar service after the sale.



This 25-year-old ambulance has been in two rollover accidents and was recently remounted on its 7th chassis!

EXCELLANCE quality construction stands the test of time.

You deserve the best possible value for your investment that will “pay for itself” many times over. Each time a unit is remounted, the structural warranty is automatically extended another 25 years. This ensures the best possible value for your investment, one that will pay for itself time after time.